

14th Floor, Centre Tower 3300 Bloor Street West Toronto, Ontario Canada M8X 2X4 Tel.: 416.734.3300

Fax: 416.231.1626 Toll Free: 1.877.682.8772

www.tssa.org

July 13, 2015

SUSAN TURNER
PARKER HANNIFIN CANADA INC
4635 DURHAM RD S
GRIMSBY ON L3M 4G4
CA

Service Request Type.: BPV-National BC

Service Request No.: 1613518

Your Reference No.: RL SERIES RELIEF VALVES - RENEW CRN 0C9895.5

Registered to.: PARKER HANNIFIN CANADA INC

Dear SUSAN TURNER,

Please find enclosed the original response from BC, registered under the CRN No.: 0C9895.51.

As all jurisdictional fees are handled by the Technical Standards and Safety Authority (TSSA), you do not pay any jurisdictions directly.

Should you have any questions or require further assistance, I will be happy to assist you. For general enquiries, please contact a Customer Service Advisor at 1.877.682.TSSA (8772) or e-mail customerservices@tssa.org. When contacting TSSA regarding this file, please refer to the Service Request number provided above.

Yours truly,

Tanya Francis
Administrative Assistant_ BPV Engineering

Tel.: 416-734-3423 Fax: 416-231-6183 Email:tfrancis@tssa.org



505 - 6th Street, Suite 200 New Westminster, BC V3L 0E1

> Toll Free: 1-866-566-SAFE Fax: (778) 396 - 2064 www.safetyauthority.ca

TECHNICAL STANDARDS & SAFETY AUTHORITY 14TH FLOOR CENTRE TOWER-3300 BLOOR STREE TORONTO ON M8X 2X4

Date:

June 10, 2015

Account #: 35231

Journal #: 62625

Our File #: 5539073

Attn: TANYA FRANCIS

Application for Design Registration

The design, as detailed in your, TSSA Service Request No: 1613518, for a Fitting is accepted for registration as

follows:

Registered To: PARKER HANNIFIN

CRN:

0C9895.51

INSTRUMENTATION

MAWT: 400 deg F

MAWP: 400 psig

Drawing #: Catalog 4135-CV, Dec 2010

Conditions Of Registration:

Registration renewal of RL Series Relief Valves as per scope of registation sheet.

This design was registered based on a technical review performed by the province of initial registration in accordance with the Association of Chief Inspectors policy on reciprocal recognition of design review.

Reviewer's Notes:

As required by CSA B51 4.2.1, this registration expires on March 18, 2025. This CRN is valid until the expiry date as long as the Manufacturer maintains a valid quality control program verified by an acceptable third-party agency until that date. Should the certification of the quality control program lapse before the expiry date, this registration shall become void.

Contact me if you have any questions. The invoice for registration will be forwarded under separate cover.

SHARON PETERS

boiler.designregistration@safetyauthority.ca Design Administration

cc:



Parker Hannifin Corporation Instrumentation Products Division 1005 A Cleaner Way Huntsville, AL 35805 Office 256-881-2040 Fax 256-881-5072

December 16, 2014

SCOPE OF REGISTRATION RENEWAL 0C9895.5

The scope of this registration renewal are the RL Series Relief Valve valves listed on pages 40 through 43 of Catalog 4135-CV, Check Valves, Filters, and Relief Valves, dated December 2010. These are the same valves and materials as were covered by the existing registration. The design of these valves has not changed since the original registration. A change was made to previous catalog 4131-RL (April 2005). The contents of that catalog were incorporated in a consolidated line catalog (4135-CV) as listed above.

These valves are not to be used as primary pressure relief devices for overpressure protection.

Fredrick Roy, P.E

Senior Engineer

Certifications and Registrations

December 16, 2014



