

14th Floor, Centre Tower 3300 Bloor Street West Toronto, Ontario Canada M8X 2X4 Tel.: 416.734.3300 Fax: 416.231.1626

Toll Free: 1.877.682.8772

www.tssa.org

June 24, 2015

SUSAN TURNER
PARKER HANNIFIN INSTRUMENTATION GROUP CANADA
4635 DURHAM RD S
GRIMSBY ON L3M 4G4
CA

Service Request Type.: BPV-National BC

Service Request No.: 1618142

Your Reference No.: INSTRUMENTATION HAND VALVES

Registered to.: PARKER HANNIFIN INSTRUMENTATION GROUP CANADA

Dear SUSAN TURNER,

Please find enclosed the original response from BC, registered under the CRN No.: 0C9963.51.

As all jurisdictional fees are handled by the Technical Standards and Safety Authority (TSSA), you do not pay any jurisdictions directly.

Should you have any questions or require further assistance, I will be happy to assist you. For general enquiries, please contact a Customer Service Advisor at 1.877.682.TSSA (8772) or e-mail customerservices@tssa.org. When contacting TSSA regarding this file, please refer to the Service Request number provided above.

Yours truly,

Tanya Francis
Administrative Assistant\_ BPV Engineering

Tel.: 416-734-3423 Fax: 416-231-6183 Email:tfrancis@tssa.org



505 - 6th Street, Suite 200 New Westminster, BC V3L 0E1

> Toll Free: 1-866-566-SAFE Fax: (778) 396 - 2064 www.safetyauthority.ca

TECHNICAL STANDARDS & SAFETY AUTHORITY 14TH FLOOR CENTRE TOWER-3300 BLOOR STREE TORONTO ON M8X 2X4

Date:

May 11, 2015

Account #: 35231

Journal #: 62498

Our File #: 5537481

Attn: TANYA FRANCIS

Application for Design Registration Re:

The design, as detailed in your, TSSA Service Request No: 1618142, for a Fitting is accepted for registration as

follows:

Registered To: PARKER HANNIFIN

CRN:

0C9963.51

INSTRUMENTATION PRODUCTS

**DIV EUROPE** 

**Drawing #: 4190-HV** 

Drawing Revision: Revised September 2002

## Conditions Of Registration:

Registration renewal of H Series Instrumentation Hand Valves.

This design was registered based on a technical review performed by the province of initial registration in accordance with the Association of Chief Inspectors policy on reciprocal recognition of design review.

## Reviewer's Notes:

As required by CSA B51 4.2.1, this registration expires on March 30, 2025. This CRN is valid until the expiry date as long as the Manufacturer maintains a valid quality control program verified by an acceptable third-party agency until that date. Should the certification of the quality control program lapse before the expiry date, this registration shall become void.

Contact me if you have any questions. The invoice for registration will be forwarded under separate cover.

## SHARON PETERS

boiler.designregistration@safetyauthority.ca Design Administration

cc: