

14th Floor, Centre Tower 3300 Bloor Street West Toronto, Ontario Canada M8X 2X4 Tel.: 416.734.3300

Fax: 416.231.1626 Toll Free: 1.877,682.8772

www.tssa.org

October 27, 2015

SUSAN TURNER
PARKER HANNIFIN CANADA INC
4635 DURHAM RD S
GRIMSBY ON L3M 4G4
CA

Service Request Type.: BPV-National BC

Service Request No.: 1678130

Your Reference No.: PR SERIES VALVES

Registered to .: PARKER HANNIFIN - INSTRUMENTATION PRODUCTS DIVISION

Dear SUSAN TURNER.

Please find enclosed the original response from BC, registered under the CRN No.: 0C10224.51.

As all jurisdictional fees are handled by the Technical Standards and Safety Authority (TSSA), you do not pay any jurisdictions directly.

Should you have any questions or require further assistance, I will be happy to assist you. For general enquiries, please contact a Customer Service Advisor at 1.877.682.TSSA (8772) or e-mail customerservices@tssa.org. When contacting TSSA regarding this file, please refer to the Service Request number provided above.

Yours truly,

Tanya Francis Administrative Assistant\_ BPV Engineering

Tel.: 416-734-3423 Fax: 416-231-6183 Email:tfrancis@tssa.org



505 - 6th Street, Suite 200 New Westminster, BC V3L 0E1

> Toll Free: 1-866-566-SAFE Fax: (778) 396 - 2064 www.safetyauthority.ca

TECHNICAL STANDARDS & SAFETY AUTHORITY 14TH FLOOR CENTRE TOWER-3300 BLOOR STREE TORONTO ON M8X 2X4

Date:

September 2, 2015

Account #: 35231 Journal #: 63460 Our File #: 5552138

Attn: TANYA FRANCIS

Re:

Application for Design Registration

The design, as detailed in your, TSSA SR# 1678130, for a Fitting is accepted for registration as follows:

Registered To: PARKER HANNIFIN INC.

CRN:

0C10224.51

MAWT: 232 deg C

MAWP: 3000 psig

Drawing #: Cat: 4121-BV (May 2011)

## Conditions Of Registration:

Reg'n renewal of PR Series Ball & Plug Valves as listed on pages 12 through 15 of Cat: 4121-BV (May 2011). This design was registered based on a technical review performed by the province of initial registration in accordance with the Association of Chief Inspectors policy on reciprocal recognition of design review.

## Reviewer's Notes:

As required by CSA B51 4.2.1, this registration expires on June 24, 2025. This CRN is valid until the expiry date as long as the Manufacturer maintains a valid quality control program verified by an acceptable third-party agency until that date. Should the certification of the quality control program lapse before the expiry date, this registration shall become void.

Contact me if you have any questions. The invoice for registration will be forwarded under separate cover.

## SHARON PETERS

boiler.designregistration@safetyauthority.ca **Design Administration** 

cc: